

COBBLESTONE STRUCTURES

May 14-18, 1979

SENECA COUNTY

- 1 - Smith, Dublin Rd., W of Lasher
- 2 - Stone Church, Stone Church Rd. (1839)
- 3 - Fisk, Dublin Rd., E of Co. Rd. 108
- 4 - Grillone, Stone Church Rd.
- 5 - Hoffman, Stone Church Rd.
- 6 - Kunes, Birdsley & Bedell Rd.
- 7 - Hicks, Odell Rd.
- 8 - Wolf, Birdsley Rd.
- 9 - Houghton, Old State Rd. (Rt. 318)
- 10 - Strong, Magee Corners (1825)
- 11 - Adler, 1442 Gravel Rd
- 12 - Lawrence, 1429 E Tyre Rd.
- 13 - Rogers, 1423 Mays Point Rd.
- 13A - Barn, Lay Rd. (1859)
- 14 - Hahn, Rt. 89, E. Varick (1833)
- 15 - Paine, Birdsley Rd.
- 16 - Winter, Hog House, Garrett Rd.
- 17 - Mulcahy, Smoke House, Dublin & Avery Rds.
- 18 - Caulkins, 3333 Lower Lake Rd.
- 19 - Ridley, 3333 Ritter Rd. (1843)
- 20 - Freier, 3792 Post Rd.

SENECA COUNTY

Sen - 15

A small 1½ story house on Birdsley Road lacks quoins, but has the corners covered by pieces of wood, giving the appearance of pilasters. Window lintels are made of wood. Stones vary in size and color, and are irregular in shape. Mortar is spread between the stones with no special embellishments.

Sen - 16

This small structure was used as a hoghouse. It has been extensively repaired, so that little of the original construction can be recognized, but at the front corners at ground level, typical cobblestone construction can be recognized. Stones are fairly large and are irregular. They are set in mortar with definite horizontal strips. Between the stones, the mortar extends simply between the upper and lower horizontals.

Sen - 17

A small smokehouse at Dublin and Avery Roads has brick corners (not really quoins) and its stones are large and irregular, and of various colors. The mortar is v shaped at the edge, while the verticals are embellished slightly. The mortar contains large pieces of calcium carbonate.

Sen - 18

The cobblestone on Ferry Farm at 3333 Lower Lake Road is a two story main building with a one story wing on the south side. The wing appears to be a later addition. Quoins are uniform blocks of gray limestone. Window lintels are of the same material with several in the back wall being made of cut blocks of gray limestone. Stones are irregular and are not smoothed. The horizontal mortar is pointed outward, while the vertical spaces between stones contain pyramids of mortar with their bases cut off at the bottom of the row of stones. There are three rows of stones per quoin.

Sen - 19

At 3333 Ritter Road, there is a one and one-half story house with a center entrance and two windows on each side of it. Over the lintel of each of these windows, there is a crude numeral built into the wall by arrangement of stones. These numerals, reading from left to right, form the date the house was built, 1843. Quoins are irregular but smoothed, and are arranged in four rows per quoin. The mortar between stones contains shallow pyramids, cut off at the bottom.

Sen-20

At 3792 Post Road, there is a 2½ story house, the first floor of which is cobblestone. At the corners, there are cement pilasters instead of quoins. Stones are irregular and vary in size and color. The vertical mortar between the stones is raised in cylinders which do not meet the surface of either of the horizontal strips of mortar